

Brooks Elementary School

Gervais SD 1

Mari_sch47A

Building Type	County
School	Marion
Street	
5035 Rockdale St NE	
City	State Zip
Brooks	OR 97305
Latitude	Longitude
45.04948	122.95506
Tracking Code	Inspection Date
RVS in 2006	7/28/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Secondary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Brooks Elementary School

Final RVS Score

Final Type	Final Score
PC1	1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Brooks Elementary School

Mari_sch47A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
243	1990	1990	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
32584	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
W Field Verified Year Built			
SW Plan Irregularity Primary			
S Elevation View			
SE Vertical Irregularity Primary			
SE Elevation View			
S General Site A AND MODULAR			
W General Site MODULAR DETAIL			
N General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Brooks Elementary School

Mari_sch47A



N Elevation View



NW Elevation View



NW Secondary Structural Type
ON GYM



N Secondary Structural Type
PC1 ON GYM WALL - THIN MEMB IS STL TUBE COL



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries