

# Stayton Middle School

Mari\_sch50A

North Santiam SD 29J

Building Type		County	
School		Marion	
Street			
1021 Shaff Rd			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.8108		122.80365	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stayton Middle School

## Final RVS Score

Final Type

Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
603	1970	1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
84296	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Very Irregular Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S General Site



SE General Site



E General Site

N Pounding Potential  
bldg D on left and A on rightNW Primary Structural Type  
RM1W Field Verified Year Built  
1970

S General Site



W Vertical Irregularity Primary



NW General Site





S General Site





# Stayton Middle School

Mari\_sch50B

North Santiam SD 29J

Building Type		County	
School		Marion	
Street			
1021 Shaff Rd			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.8112		122.80398	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stayton Middle School

## Final RVS Score

Final Type

Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
603		1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
84296	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW General Site



W Vertical Irregularity Primary



E General Site  
this is from inside bldg A looking at B. The two buildings meet at the corner with a little over lap, see plan view.



N General Site



W Primary Structural Type  
RM1



# Stayton Middle School

North Santiam SD 29J

Mari\_sch50C

Building Type		County	
School		Marion	
Street			
1021 Shaff Rd			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.81128		122.80469	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stayton Middle School

## Final RVS Score

Final Type

Final Score

RM1

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
603		1970	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
84296	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE General Site



SW General Site



SW General Site



E General Site



W General Site



# Stayton Middle School

North Santiam SD 29J

Mari\_sch50D

Building Type		County	
School		Marion	
Street			
1021 Shaff Rd			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.81032		122.80368	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	-0.5	0	1.6	0	-0.6	0	5.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stayton Middle School

## Final RVS Score

Final Type

Final Score

W1

5.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
603		1970	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
84296	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:Other (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE    General Site