

Cascade Senior High School

Mari_sch61A

Cascade SD 5

Building Type		County	
School		Marion	
Street			
10226 Marion Rd SE			
City	State	Zip	
Turner	OR	97392	
Latitude		Longitude	
44.80836		122.91455	
Tracking Code		Inspection Date	
RVS in 2006		7/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Cascade Senior High School

Final RVS Score

Final Type

Final Score

C2

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
778		1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
154000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW General Site



W Vertical Irregularity Primary



NE General Site




SE General Site

Cascade Senior High School

Mari_sch61B

Cascade SD 5

Building Type		County	
School		Marion	
Street			
10226 Marion Rd SE			
City	State	Zip	
Turner	OR	97392	
Latitude		Longitude	
44.80798		122.91491	
Tracking Code		Inspection Date	
RVS in 2006		7/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cascade Senior High School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
778	1968	1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
154000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
Other: Ornamental Hazard Over Exit	None
None	None



NE Falling Hazard



SE General Site



E General Site



NE Falling Hazard
Brick




W Plan Irregularity Primary



SE Pounding Potential
and falling hazard



N Building Quality



NW Falling Hazard



NW General Site



NW General Site

