

Oregon School for the Deaf

OR Dep. of Education

Mari sch93A

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96597	123.02334	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

C2 0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93A

Enrollment 124	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1914	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other None None	Steps in Elevation View: 2 to 3 Changes None None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit Other: Brick Veneer None	None None None



NE General Site



N Primary Structural Type



NE Pounding Potential



NW Basement



NW Vertical Irregularity Primary



W General Site



SW Plan Irregularity Primary



S General Site



W General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



SW General Site



SW Pounding Potential

Oregon School for the Deaf

OR Dep. of Education

Mari sch93B

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.9647	123.02342	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

C2 0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93B

Enrollment 124	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1914	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Soft Story	
Reentrant Corners: L Shaped		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
Other: General		Poor Concrete	
None		None	
None		None	
			
NW General Site	W General Site	NW Plan Irregularity Primary	
			
SW Vertical Irregularity Primary	SE General Site	S Pounding Potential	
			
S Pounding Potential	NW Pounding Potential	NE Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



N Building Quality



Oregon School for the Deaf

OR Dep. of Education

Mari sch93C

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96484	123.02219	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

W2	2.5
----	-----

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93C

Enrollment 124	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1914	Est. Decade Built 1940
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: H Shaped Reentrant Corners: L Shaped (Adjacent Build/Entity) None		Vertical Irregularities Building On Hill or Sloped Site None None	
Falling Hazards Other: Brick Veneer Unreinforced Chimneys Other: General		Poor Conditions Poor Masonry None None	
 NW General Site		 W Falling Hazard	
 SW General Site		 W General Site	
 E General Site		 NE General Site	
 NE Falling Hazard		 N General Site	
 NE General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93C



Oregon School for the Deaf

OR Dep. of Education

Mari sch93D

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96543	123.0205	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type	Final Score
------------	-------------

W2 2.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93D

Enrollment 124	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1914	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
W General Site		W Primary Structural Type	
		NW General Site	
			
N General Site		N Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari_sch93E

Building Type	County
School	Marion
Street	
999 Locust St	
City	State Zip
Salem	OR 97303
Latitude	Longitude
44.96626	123.01967
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oregon School for the Deaf

Final RVS Score

Final Type	Final Score
C2	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93E

Enrollment 124	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1914	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
 SW General Site		 SW General Site	
		 S Primary Structural Type	
 NW Falling Hazard		 W General Site	
		 W General Site	
 W General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari_sch93F

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96608	123.02067	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

W1	3.9
----	-----

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93F

Enrollment 124	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1914	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		None None None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys None None		None None None	
 NW Basement		 SE General Site	
 SE Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari sch93G

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96579	123.02201	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93G

Enrollment 124	Year Built (Field Verified) 1971	Year Built (Alt. Source) 1914	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 SE Primary Structural Type		 NW Plan Irregularity Primary	
 NW General Site		 SW General Site	
 W General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari sch93H

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96558	123.02308	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type	Final Score
------------	-------------

C2 0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93H

Enrollment 124	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1914	Est. Decade Built 1920
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
NE General Site		SE Falling Hazard	
		E Pounding Potential	
		W Primary Structural Type	
		S Pounding Potential	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari sch93I

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96645	123.02306	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	0	0	0	0	-0.8	1.5
Secondary	RM1	2.8	0	-0.5	0	0	0	0	-0.4	1.9
Tertiary	W1	4.4	0	-0.5	0	0	0	0	0	3.9

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

C2 1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch931

Enrollment 124	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1914	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Pounding Potential		 E Pounding Potential	
		 SE Primary Structural Type	
 SE General Site		 W General Site	
		 NW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari_sch93J

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.96654	123.02414	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



Oregon School for the Deaf

Mari_sch93J

Enrollment 124	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1914	Est. Decade Built 1970
Total Area (square ft) 	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 NW General Site		 SW General Site	
 E Plan Irregularity Primary		 S General Site	
 E Pounding Potential		 SE Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

OR Dep. of Education

Mari sch93K

Building Type	County	
School	Marion	
Street		
999 Locust St		
City	State	Zip
Salem	OR	97303
Latitude	Longitude	
44.9652	123.02312	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Oregon School for the Deaf

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oregon School for the Deaf

Mari_sch93K

Enrollment 124	Year Built (Field Verified) 1914	Year Built (Alt. Source) 1914	Est. Decade Built 1910
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E	Primary Structural Type	E	Primary Structural Type
			
		SE	Poor Condition
			
S	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries