

William P Lord High School

ODE YCEP District

Mari_sch94A

Building Type	County
School	Marion
Street	
2630 N Pacific Hwy	
City	State Zip
Woodburn	OR 97071
Latitude	Longitude
45.15562	122.82007
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Tertiary	S1	2.8	0	-0.5	0	0	0	-0.6	0	1.7

William P Lord High School

Final RVS Score

Final Type	Final Score
RM1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

William P Lord High School

Mari_sch94A

Enrollment 372	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Lateral-Force-Resistance in One Direction Only		None	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
Reentrant Corners: Other		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
SW General Site		SE Pounding Potential	
		S Pounding Potential	
			
SE Falling Hazard		S Primary Structural Type	
			
W General Site		W General Site	
			
Ends of building maybe wood framed		NW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



W Primary Structural Type
Steel colum support wooden beams




NW Primary Structural Type
Base of column



NW Primary Structural Type
Top of Column



N Pounding Potential
bldg B on left A on right.



W Primary Structural Type
brick wall goes through building. There is about a 3 inch gap
between the brick walls, possibly rein

William P Lord High School

ODE YCEP District

Mari_sch94B

Building Type	County
School	Marion
Street	
2630 N Pacific Hwy	
City	State Zip
Woodburn	OR 97071
Latitude	Longitude
45.1556	122.81976
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

William P Lord High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

William P Lord High School

Mari_sch94B

Enrollment 372	Year Built (Field Verified) 	Year Built (Alt. Source) 	Est. Decade Built 1970
Total Area (square ft) 	Number of Stories 1	Basement No	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Primary Structural Type		 W Pounding Potential	
 W General Site bldg C on left		 NE General Site building A in back	
 S General Site		 S Falling Hazard	
 N Building Quality			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

William P Lord High School

ODE YCEP District

Mari_sch94C

Building Type	County
School	Marion
Street	
2630 N Pacific Hwy	
City	State Zip
Woodburn	OR 97071
Latitude	Longitude
45.15563	122.81959
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary	C3	1.6	0	-0.5	0	0	0	-0.4	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

William P Lord High School

Final RVS Score

Final Type	Final Score
C3	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

William P Lord High School


Mari_sch94C

Enrollment 372	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards Other: General Other: Brick Veneer None		Poor Conditions None None None	
 N General Site		 N General Site	
		 W Primary Structural Type	
 NE Primary Structural Type		 S General Site	
		 SE General Site	
 SW General Site		 S Pounding Potential	
		 S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



W Primary Structural Type
inside classroom Concrete column. Minor cracks where
columns meet wall.



William P Lord High School

ODE YCEP District

Mari_sch94D

Building Type School	County Marion	
Street 2630 N Pacific Hwy		
City Woodburn	State OR	Zip 97071
Latitude 45.15453	Longitude 122.81885	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

William P Lord High School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

William P Lord High School

Mari_sch94D

Enrollment 372	Year Built (Field Verified) 	Year Built (Alt. Source) 	Est. Decade Built 1960
Total Area (square ft) 	Number of Stories 1	Basement No	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other (Adjacent Build/Entity) None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 NW Pounding Potential		 NE Primary Structural Type C2 walls on the left.	
 NW General Site		 W General Site	
 SW Pounding Potential mech bldg in back bldg D in front.		 NE General Site Mech building in white.	
 NW General Site		 NW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

William P Lord High School

ODE YCEP District

Mari_sch94E

Building Type	County
School	Marion
Street	
2630 N Pacific Hwy	
City	State Zip
Woodburn	OR 97071
Latitude	Longitude
45.15647	122.82069
Tracking Code	Inspection Date
RVS in 2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

William P Lord High School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

William P Lord High School

Mari_sch94E

Enrollment 372	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Parapets: General Other: Brick Veneer None		Poor Conditions None None None	
 SW General Site		 SE Pounding Potential	
 NE Primary Structural Type Concrete		 N General Site	
 W Falling Hazard		 NW General Site	
 N General Site		 NW Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries