


Boardman RFPD

Boardman RFPD

Morr_fir02A

Building Type Fire - RFPD	County Morrow	
Street 300 SW Wilson Ln		
City Boardman	State OR	Zip 97818
Latitude 45.82822	Longitude 119.70599	
Tracking Code RVS in 2006	Inspection Date 7/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Boardman RFPD

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Vertical Irregularity Primary	S	Primary Structural Type



Boardman RFPD

Boardman RFPD

Morr_fir02B

Building Type Fire - RFPD	County Morrow	
Street 302 SW Wilson Ln		
City Boardman	State OR	Zip 97818
Latitude 45.82821	Longitude 119.7066	
Tracking Code RVS in 2006	Inspection Date 7/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Boardman RFPD

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	