

Maywood

Mt Hood CC

Mult_coc12A

Building Type		County	
Community_College		Multnomah	
Street			
10100 NE Prescott			
City		State	Zip
Portland		OR	97220
Latitude		Longitude	
45.55467		122.55855	
Tracking Code		Inspection Date	
RVS in 2006		6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

Maywood

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)

Mt Hood CC - Maywood Park Campus
10100 NE Prescott St
Portland, OR 97220




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None


Falling Hazards	Poor Conditions
None	None
None	None
None	None




NW Vertical Irregularity Primary



S Elevation View



S Elevation View



N Other
LINE BET A AND C



Maywood

Mt Hood CC

Mult_coc12B

Building Type		County	
Community_College		Multnomah	
Street			
10100 NE Prescott			
City	State	Zip	
Portland	OR	97220	
Latitude		Longitude	
45.55492		122.55864	
Tracking Code		Inspection Date	
RVS in 2006		6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	-1.5	-0.5	-1.2	0	-0.4	0	0	-1.1
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	C3	1.6	-1	-0.5	-0.2	0	-0.4	0	0	-0.5

Maywood

Final RVS Score

Final Type

Final Score

C1

-1.1

FEMA-154 Collapse Potential

Very High (100%)

Mt Hood CC - Maywood Park Campus
10100 NE Prescott St
Portland, OR 97220



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Seismic Upgrade



E Primary Structural Type



NW Elevation View



Maywood

Mt Hood CC

Mult_coc12C

Building Type		County	
Community_College		Multnomah	
Street			
10100 NE Prescott			
City		State	Zip
Portland		OR	97220
Latitude		Longitude	
45.55468		122.55826	
Tracking Code		Inspection Date	
RVS in 2006		6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary	C2	2.8	0	0	0	0	-0.4	0	0	2.4
Tertiary		0	0	0	0	0	0	0	0	0

Maywood

Final RVS Score

Final Type

Final Score

C2

2.4

FEMA-154 Collapse Potential

Low (<1%)

Mt Hood CC - Maywood Park Campus
10100 NE Prescott St
Portland, OR 97220



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



N Primary Structural Type

