

Cascade - Student Services

Mult_coc21A

Portland CC

Building Type		County	
Community_College		Multnomah	
Street			
705 N Killingsworth St			
City	State	Zip	
Portland	OR	97217	
Latitude		Longitude	
45.56391		122.67447	
Tracking Code		Inspection Date	
RVS in 2006		6/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	-1.5	-0.5	0	1.4	-0.4	0	0	2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cascade - Student Services

Final RVS Score

Final Type


Final Score

S2

2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1996	1996	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
34000	3	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Very Irregular Changes
None	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



NE Vertical Irregularity Primary



NW Elevation View



S Elevation View



S General Site