

Portland F & R - Station 17 Hayden Island

Mult_fir19A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
848 N Tomahawk Drive			
City	State	Zip	
Portland	OR	97217	
Latitude		Longitude	
45.6097		122.67575	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 17 Hayden Island

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1994	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4938		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions