


# Portland Police Bureau Sunshine Division Office

City of Portland

Mult\_pol06A

Building Type Police - City	County Multnomah	
Street 687 N Thompson St		
City Portland	State OR	Zip 97227
Latitude 45.53884	Longitude 122.67362	
Tracking Code RVS in 2006	Inspection Date 7/10/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	-1	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland Police Bureau Sunshine Division Office

## Final RVS Score

Final Type	Final Score
C2	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Portland Police Bureau Sunshine Division Office

Mult\_pol06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1929	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: General		None	
None		None	
			
S	Falling Hazard	S	Building Name



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Portland Police Bureau Sunshine Division Warehouse

Mult\_pol06B

City of Portland

Building Type Police - City	County Multnomah	
Street 687 N Thompson St		
City Portland	State OR	Zip 97227
Latitude 45.53887	Longitude 122.6734	
Tracking Code RVS in 2006	Inspection Date 7/10/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary	URM	1.8	-1	-0.5	-0.2	0	-0.4	0	0	-0.3

Portland Police Bureau Sunshine Division Warehouse

## Final RVS Score

Final Type	Final Score
URM	-0.3

## FEMA-154 Collapse Potential


Very High (100%)



OregonGeology

# Portland Police Bureau Sunshine Division Warehouse

Mult\_pol06B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1929	1910
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
S	Primary Structural Type	SE	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries