

# Prescott Elementary School

Parkrose SD 3

Mult\_sch124A

|                   |                 |       |
|-------------------|-----------------|-------|
| Building Type     | County          |       |
| School            | Multnomah       |       |
| Street            |                 |       |
| 10410 NE Prescott |                 |       |
| City              | State           | Zip   |
| Portland          | OR              | 97220 |
| Latitude          | Longitude       |       |
| 45.55509          | 122.55529       |       |
| Tracking Code     | Inspection Date |       |
| RVS in 2006       | 6/29/2006       |       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | -2         | 0          | 0        | 0          | -0.4   | 0      | 0      | 1.4       |
| Secondary | C2   | 2.8         | -1         | 0          | 0        | 0          | -0.4   | 0      | 0      | 1.4       |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Prescott Elementary School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2         | 1.4         |

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Prescott Elementary School

Mult\_sch124A

|   |                                     |   |                           |
|---|-------------------------------------|---|---------------------------|
| Enrollment<br>371   | Year Built (Field Verified)<br>1959 | Year Built (Alt. Source)<br>1950  | Est. Decade Built<br>1950 |
| Total Area (square ft)<br>37740   | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities<br>Out of Plane Lateral-Force-Resistance Elements<br>None   |                                     | Vertical Irregularities<br>Steps in Elevation View: 2 to 3 Changes<br>None  |                           |
| Falling Hazards<br>Unreinforced Chimneys<br>Other: General<br>None  |                                     | Poor Conditions<br>None   |                           |
| <br>NW Plan Irregularity Primary      |                                     | <br>SW Elevation View            |                           |
| <br>NW Plan Irregularity Primary    |                                     | <br>NE Plan Irregularity Primary |                           |
| <br>E Vertical Irregularity Primary |                                     | <br>E Falling Hazard           |                           |

# Prescott Elementary School

Parkrose SD 3

Mult\_sch124B

|                   |                 |
|-------------------|-----------------|
| Building Type     | County          |
| School            | Multnomah       |
| Street            |                 |
| 10410 NE Prescott |                 |
| City              | State Zip       |
| Portland          | OR 97220        |
| Latitude          | Longitude       |
| 45.55438          | 122.55518       |
| Tracking Code     | Inspection Date |
| RVS in 2006       | 6/29/2006       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | C2   | 2.8         | 0          | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 1.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Prescott Elementary School

### Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2         | 1.9         |

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Prescott Elementary School

Mult\_sch124B

|   |                                     |   |                           |
|---|-------------------------------------|---|---------------------------|
| Enrollment<br>371   | Year Built (Field Verified)<br>1959 | Year Built (Alt. Source)<br>1959  | Est. Decade Built<br>1960 |
| Total Area (square ft)<br>37740   | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities   |                                     | Vertical Irregularities   |                           |
| Reentrant Corners: Other  |                                     | None  |                           |
| Torsion: Eccentric Stiffness  |                                     | None  |                           |
| None  |                                     | None  |                           |
| Falling Hazards   |                                     | Poor Conditions   |                           |
| Other: General  |                                     | None  |                           |
| None  |                                     | None  |                           |
| None  |                                     | None  |                           |
|   |                                     |   |                           |
| N Falling Hazard  | NE Primary Structural Type          | SE Plan Irregularity Primary  |                           |
|  |                                     |  |                           |
| SE Plan Irregularity Primary  | S Plan Irregularity Primary         |   |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries