

Shaver Elementary School

Parkrose SD 3

Mult_sch125A

| | |
|------------------|-----------------|
| Building Type | County |
| School | Multnomah |
| Street | |
| 3701 NE 131st Pl | |
| City | State Zip |
| Portland | OR 97230 |
| Latitude | Longitude |
| 45.54946 | 122.52879 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 7/13/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | -1 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 0.9 |
| Secondary | RM1 | 2.8 | -1 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 0.9 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Shaver Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 0.9 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shaver Elementary School

Mult_sch125A

| | | | |
|---|-------------------------------------|--|---------------------------|
| Enrollment 322 | Year Built (Field Verified) 1963 | Year Built (Alt. Source) 1963 | Est. Decade Built 1960 |
| Total Area (square ft) 46858 | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None | | Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None | |
| Falling Hazards Unreinforced Chimneys Other: General None | | Poor Conditions None | |
|  | |  | |
| E Secondary Structural Type | | E Secondary Structural Type | |
|  | | E Field Verified Year Built | |
|  | |  | |
| E Primary Structural Type | | E Elevation View | |
|  | | E General Site CONN TO B | |
|  | |  | |
| NE Plan Irregularity Primary | | N Falling Hazard | |
|  | | NW Primary Structural Type | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shaver Elementary School

Mult_sch125A



SW Elevation View



S Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shaver Elementary School

Parkrose SD 3

Mult_sch125B

| | |
|------------------|-----------------|
| Building Type | County |
| School | Multnomah |
| Street | |
| 3701 NE 131st Pl | |
| City | State Zip |
| Portland | OR 97230 |
| Latitude | Longitude |
| 45.54898 | 122.52823 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 7/13/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | -1 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 0.9 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Shaver Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 0.9 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shaver Elementary School

Mult_sch125B

| | | | |
|---|-------------------------------------|--|---------------------------|
| Enrollment 322 | Year Built (Field Verified) 1963 | Year Built (Alt. Source) 1960 | Est. Decade Built 1960 |
| Total Area (square ft) 46858 | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: Single Change (Adjacent Building/Entity) | |
| Torsion: Eccentric Stiffness | | None | |
| Reentrant Corners: Other (Adjacent Build/Entity) | | None | |
| Falling Hazards | | Poor Conditions | |
| Other: General | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| N Falling Hazard | W General Site | SW Plan Irregularity Primary | |
|  | |  | |
| S Primary Structural Type | SE Plan Irregularity Secondary | E General Site | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries