

## David Douglas SD 40

Mult sch15A

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7

Gilbert Park Elementary School

### Final RVS Score

Final Type

Final Score

W2

0.5

## FEMA-154 Collapse Potential

High (>10%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
616		1954	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
49839	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity	None
None	None

Falling Hazards	Poor Conditions
Other: General	None
None	None
None	None



N Vertical Irregularity Primary



NW Elevation View



W Elevation View

S Elevation View  
WOOD SIDED BLDG TO LEFT IS THE 2 ROOM CLASSROOM STRUCTURESE Plan Irregularity Primary  
T11 SIDING IS ON STORAGE BUMP-OUT

E Elevation View



## David Douglas SD 40

Mult sch15B

A photograph of a large, white, gabled building, likely a school or community center, with a basketball hoop in the foreground and a grassy hillside to the right. The building has several windows and doors, some of which are painted blue. A tall light pole stands near the building. The foreground shows a paved area with white lines, possibly a basketball court. The background features a line of evergreen trees under a cloudy sky.

Gilbert Park Elementary School

### Final RVS Score

Final Type

Final Score

W2

### 3.4

## FEMA-154 Collapse Potential

Low (<1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
616		1954	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
49839	1	No	No

Plan Irregularities	Vertical Irregularities
None	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



W Falling Hazard



NE Elevation View



# Gilbert Park Elementary School

Mult\_sch15C

David Douglas SD 40

Building Type		County	
School		Multnomah	
Street			
13132 SE Ramona St			
City	State	Zip	
Portland	OR	97236	
Latitude		Longitude	
45.4791		122.52867	
Tracking Code		Inspection Date	
RVS in 2006		7/11/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Gilbert Park Elementary School

## Final RVS Score

Final Type

Final Score

W2

4.9

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
616		1954	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
49839	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View



SW Vertical Irregularity Primary