

Harold Oliver Primary School Center

Centennial SD 28J

Mult_sch151A

Building Type	County
School	Multnomah
Street	
15811 Se Main St	
City	State Zip
Portland	OR 97233
Latitude	Longitude
45.51436	122.50029
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Harold Oliver Primary School Center

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harold Oliver Primary School Center

Mult_sch151A

Enrollment 506	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 45815	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
SE Building Name	SE Secondary Structural Type	S Elevation View	
			
W Primary Structural Type	W Plan Irregularity Primary	W Falling Hazard CHIMNEY AND CANOPY	
			
NE Elevation View	SE Elevation View	E Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harold Oliver Primary School Center

Centennial SD 28J

Mult_sch151B

Building Type	County
School	Multnomah
Street	
15811 Se Main St	
City	State Zip
Portland	OR 97233
Latitude	Longitude
45.51471	122.5004
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary	S2	3	-1.5	-0.5	0	0	-0.4	0	0	0.6
Tertiary		0	0	0	0	0	0	0	0	0

Harold Oliver Primary School Center

Final RVS Score

Final Type	Final Score
S2	0.6

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harold Oliver Primary School Center

Mult_sch151B

Enrollment 506	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1980
Total Area (square ft) 45815	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Elevation View		SW Pounding Potential	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries