

Reynolds Learning Academy

Reynolds SD 7

Mult_sch161A

Building Type	County
School	Multnomah
Street	
20234 NE Halsey St	
City	State Zip
Fairview	OR 97204
Latitude	Longitude
45.53291	122.4556
Tracking Code	Inspection Date
RVS in 2006	7/14/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	S3	3.2	0	-0.5	0	0	0	0	0	2.7
Tertiary		0	0	0	0	0	0	0	0	0

Reynolds Learning Academy

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Reynolds Learning Academy

Mult_sch161A

Enrollment 173	Year Built (Field Verified) 2003	Year Built (Alt. Source) 2003	Est. Decade Built 1990
Total Area (square ft) 	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Internal Discontinuous Diaphragm (large internal opening) None	
Falling Hazards None None None		Poor Conditions None None None	
 E Primary Structural Type CAN SEE S3 FRAMES IN TALL SPACE		 N Field Verified Year Built BLT 2003	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries