

David Douglas High School

David Douglas SD 40

Mult_sch166A

Building Type	County
School	Multnomah
Street	
1001 SE 135th Ave	
City	State Zip
Portland	OR 97233
Latitude	Longitude
45.51618	122.52659
Tracking Code	Inspection Date
RVS in 2006	7/12/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9

David Douglas High School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

David Douglas High School

Mult_sch166A

Enrollment 2768	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1959	Est. Decade Built 1950		
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes		
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None			
Falling Hazards Other: General None None		Poor Conditions None None None			
	W Falling Hazard		SW Elevation View		SW Elevation View
	W Plan Irregularity Primary		E Plan Irregularity Primary		E Plan Irregularity Primary
	N Other		N Other		NW Elevation View 2002 addition.



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

David Douglas High School


Mult_sch166A



SE Building Name



E General Site



E Field Verified Year Built

David Douglas High School

David Douglas SD 40

Mult_sch166B

Building Type	County	
School	Multnomah	
Street		
1001 SE 135th Ave		
City	State	Zip
Portland	OR	97233
Latitude	Longitude	
45.51587	122.52801	
Tracking Code	Inspection Date	
RVS in 2006	7/12/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

David Douglas High School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential


High (>10%)



OregonGeology

David Douglas High School

Mult_sch166B

Enrollment 2768	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1959	Est. Decade Built 1960
Total Area (square ft) 1	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Very Irregular Changes	
Torsion: Eccentric Stiffness None		None	
Falling Hazards		Poor Conditions	
Other: General None None		Cracks None None	
			
NE Vertical Irregularity Primary		E Falling Hazard	
		SE Elevation View	
			
S Falling Hazard		SW Elevation View	
		W Secondary Structural Type	
			
N Elevation View		S Poor Condition age of wood column	
		SW Secondary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries