


Menlo Park Elementary School

Mult_sch17A

David Douglas SD 40

Building Type	County
School	Multnomah
Street	
12900 Ne Glisan St	
City	State Zip
Portland	OR 97230
Latitude	Longitude
45.52563	122.53058
Tracking Code	Inspection Date
RVS in 2006	7/13/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Menlo Park Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Menlo Park Elementary School

Mult_sch17A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
427	1952	1952	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55958	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: E Shaped		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N Secondary Structural Type			
N Elevation View			
			
NW Elevation View		W Vertical Irregularity Primary	
			
SW Falling Hazard			
SW Primary Structural Type		S Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Menlo Park Elementary School

Mult_sch17A



SE Elevation View



SE Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries