


# Riverdale Grade School

Riverdale SD 51J

Mult\_sch25A

Building Type School	County Multnomah	
Street 11733 SW Breyman Ave		
City Portland	State OR	Zip 97219
Latitude 45.44037	Longitude 122.65643	
Tracking Code RVS in 2006	Inspection Date 9/29/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	0	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverdale Grade School

## Final RVS Score

Final Type	Final Score
W2	0.3

## FEMA-154 Collapse Potential


High (>10%)



OregonGeology

# Riverdale Grade School

Mult\_sch25A

Enrollment 339	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1920	Est. Decade Built 1920
Total Area (square ft) 	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 SE Elevation View		 E Plan Irregularity Primary	
 E Vertical Irregularity Primary		 E Building Name	
 E Primary Structural Type WOOD DETAILS		 NE Elevation View	
 N Primary Structural Type WOOD DETAILS		 N Other VENEER DETAILS	
 W Plan Irregularity Primary		 W Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riverdale Grade School

Mult\_sch25A



W Vertical Irregularity Primary



W Pounding Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riverdale Grade School

Riverdale SD 51J

Mult\_sch25B

Building Type School	County Multnomah	
Street 11733 SW Breyman Ave		
City Portland	State OR	Zip 97219
Latitude 45.44011	Longitude 122.65672	
Tracking Code RVS in 2006	Inspection Date 9/29/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	0	0	2.3
Secondary	S3	3.2	0	-0.5	0	0	0	0	0	2.7
Tertiary		0	0	0	0	0	0	0	0	0

Riverdale Grade School

## Final RVS Score

Final Type	Final Score
RM1	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Riverdale Grade School

Mult\_sch25B

Enrollment 339	Year Built (Field Verified) 1947	Year Built (Alt. Source) 1920	Est. Decade Built 1940
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
NW Elevation View		W Field Verified Year Built CLASS OF 2011 REPRESENTED ON BRICK DATES	
			
E Primary Structural Type I THINK OLD GYM ROOF WAS RELACED W S3 STRUCTURE, CUSTODIAN TELLS ME WALLS ARE ORIG		E Primary Structural Type OLD BLOCK WALLS AT STAIR - BLOCK SIZE ~6"X12"	
			
N Pounding Potential		SE Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riverdale Grade School

Riverdale SD 51J

Mult\_sch25C

Building Type	County
School	Multnomah
Street	
11733 SW Breyman Ave	
City	State Zip
Portland	OR 97219
Latitude	Longitude
45.43964	122.65638
Tracking Code	Inspection Date
RVS in 2006	9/29/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	0	0	0	0.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Riverdale Grade School

## Final RVS Score

Final Type	Final Score
URM	0.3

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Riverdale Grade School

Mult\_sch25C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
339	1955	1920	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
Other: Ornamental Hazard Over Exit		None	
None		None	
			E Vertical Irregularity Primary
			E Primary Structural Type 6" THICK BRICKWORK OUTSIDE JAMB, TOTAL WALL THICKNESS > 12"
			E Falling Hazard
			E Elevation View BREEZEWAY
			W Plan Irregularity Primary
			E Primary Structural Type THICK WALLS ON E SIDE



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



E Primary Structural Type  
~16-20" ENDWALL

