

# Reynolds Middle School

Reynolds SD 7

Mult\_sch29A

Building Type School	County Multnomah	
Street 1200 NE 201st St		
City Fairview	State OR	Zip 97024
Latitude 45.53113	Longitude 122.45547	
Tracking Code RVS in 2006	Inspection Date 7/14/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Reynolds Middle School

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Reynolds Middle School

Mult\_sch29A

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity)		Vertical Irregularities Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness None		Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards Other: Ornamental Hazard Over Exit		Poor Conditions None	
Other: Brick Veneer		None	
None		None	
			
NW Plan Irregularity Secondary		W Field Verified Year Built	
		W Falling Hazard	
		SE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

## Mult sch29B

## Reynolds SD 7

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53113	122.45451	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

---

Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29B

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
SE Elevation View		NE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Reynolds SD 7

Mult\_sch29C

Building Type School	County Multnomah	
Street 1200 NE 201st St		
City Fairview	State OR	Zip 97024
Latitude 45.53171	Longitude 122.4545	
Tracking Code RVS in 2006	Inspection Date 7/14/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Reynolds Middle School

## Final RVS Score

Final Type	Final Score
RM1	1.8

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29C

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S General Site	E Elevation View	E Elevation View	
			
E Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult sch29D

Reynolds SD 7

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53174	122.45403	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type      Final Score

RM1	1.3
-----	-----

## FEMA-154 Collapse Potential

Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29D

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
S	Primary Structural Type	NE	Elevation View
		NE Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29E

Reynolds SD 7

Building Type	County
School	Multnomah
Street	
1200 NE 201st St	
City	State Zip
Fairview	OR 97024
Latitude	Longitude
45.53215	122.45406
Tracking Code	Inspection Date
RVS in 2006	7/14/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Reynolds Middle School

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Reynolds Middle School

Mult\_sch29E

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer		Poor Conditions None None None	
 SE Primary Structural Type CAULKED JT		 E General Site CONN TO F	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Reynolds SD 7

Mult sch29F

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53238	122.45407	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29F

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Primary Structural Type REINF CONC		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

## Mult sch29G

## Reynolds SD 7

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53232	122.45449	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type	Final Score
C2	1.8

## FEMA-154 Collapse Potential

### Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29G

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Primary Structural Type		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

## Mult sch29H

## Reynolds SD 7

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53207	122.45571	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type      Final Score

RM1	1.3
-----	-----

## FEMA-154 Collapse Potential

---

Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch29H

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
NE Elevation View		N General Site N CONN TO I	

# Reynolds Middle School

Mult sch29I

## Reynolds SD 7

Building Type	County	
School	Multnomah	
Street		
1200 NE 201st St		
City	State	Zip
Fairview	OR	97024
Latitude	Longitude	
45.53197	122.45616	
Tracking Code	Inspection Date	
RVS in 2006	7/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

## Reynolds Middle School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

---

Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Reynolds Middle School

Mult\_sch291

Enrollment 1022	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1990
Total Area (square ft) 168000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
NW Plan Irregularity Primary		NW Plan Irregularity Primary	
		SW Elevation View	
			
S Vertical Irregularity Primary S CONN TO H			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries