

# Riverdale High School

Mult\_sch35A

Riverdale SD 51J

Building Type	County
School	Multnomah
Street	
9727 Sw Terwilliger Blvd	
City	State Zip
Portland	OR 97219
Latitude	Longitude
45.45424	122.6843
Tracking Code	Inspection Date
RVS in 2006	9/21/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	URM	1.8	-1	-0.5	-0.2	0	-0.4	0	0	-0.3
Tertiary		0	0	0	0	0	0	0	0	0

Riverdale High School

## Final RVS Score

Final Type	Final Score
URM	-0.3

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riverdale High School

Mult\_sch35A

Enrollment 247	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1920
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
NE Vertical Irregularity Primary		E Elevation View	
		SE Number of Stories	
			
S General Site 1997 GYM		SW General Site 1997 CONST	
		SW General Site 1999 CONST	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Riverdale High School

Mult\_sch35B

Riverdale SD 51J

Building Type	County
School	Multnomah
Street	
9727 Sw Terwilliger Blvd	
City	State Zip
Portland	OR 97219
Latitude	Longitude
45.45431	122.68454
Tracking Code	Inspection Date
RVS in 2006	9/21/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverdale High School

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Riverdale High School

Mult\_sch35B

Enrollment 247	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
NE Vertical Irregularity Primary			



**OregonGeology**

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries