

Building Type School	County Multnomah	
Street 3830 Se 14th Ave		
City Portland	State OR	Zip 97202
Latitude 45.49493	Longitude 122.65088	
Tracking Code Already Retrofitted	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	0	0	0.3
Secondary										
Tertiary										0

Winterhaven School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

Moderate (>1%)

No
Planview
Available



OregonGeology

Winterhaven School

Mult_sch49A

Enrollment 339	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built
Total Area (square ft) 38092	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries