

Whitworth Elementary School

Dallas SD 2

Polk_sch12A

Building Type School	County Polk	
Street 1151 SE Miller Ave		
City Dallas	State OR	Zip 97338
Latitude 44.91748	Longitude 123.2982	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Whitworth Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Whitworth Elementary School

Polk_sch12A

Enrollment 450	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1975	Est. Decade Built 1950
Total Area (square ft) 48748	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
W General Site			

Whitworth Elementary School

Dallas SD 2

Polk_sch12B

Building Type	County	
School	Polk	
Street		
1151 SE Miller Ave		
City	State	Zip
Dallas	OR	97338
Latitude	Longitude	
44.9175	123.29721	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	0	0	0	-0.4	0	0	2.2
Secondary	C2	2.8	0	0	0	2.4	-0.4	0	0	4.8
Tertiary		0	0	0	0	0	0	0	0	0

Whitworth Elementary School

Final RVS Score

Final Type	Final Score
PC1	2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Whitworth Elementary School

Polk_sch12B

Enrollment 450	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1975	Est. Decade Built 1990
Total Area (square ft) 48748	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Primary Structural Type		S Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Whitworth Elementary School

Dallas SD 2

Polk_sch12C

Building Type	County	
School	Polk	
Street		
1151 SE Miller Ave		
City	State	Zip
Dallas	OR	97338
Latitude	Longitude	
44.91725	123.29786	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Whitworth Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Whitworth Elementary School

Polk_sch12C

Enrollment 450	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1975	Est. Decade Built 1970
Total Area (square ft) 48748	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Non-Parallel System		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries