

Sherman County Sheriff Courthouse

Sherman County

Sher_pol01A

Building Type		County	
Police - County		Sherman	
Street			
500 Court St			
City	State	Zip	
Moro	OR	97039	
Latitude		Longitude	
45.48735		120.73136	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	-0.4	0	0	0.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherman County Sheriff Courthouse

Final RVS Score

Final Type

Final Score

URM

0.6

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherman County Sheriff Courthouse

Sher_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1899	Pre 1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



E Primary Structural Type



S Field Verified Year Built



W Falling Hazard



NW General Site
CONN TO B

Sherman County Sheriff Jail

Sherman County

Sher_pol01B

Building Type		County	
Police - County		Sherman	
Street			
500 Court St			
City	State	Zip	
Moro	OR	97039	
Latitude		Longitude	
45.48744		120.73147	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	1.6	-0.2	0	0	2.6
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3

Sherman County Sheriff Jail

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1899	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Plan Irregularity Primary

