

Sherman Junior/Senior High School

Sherman County SD

Sher_sch02A

Building Type		County	
School		Sherman	
Street			
65912 High School Lp			
City	State	Zip	
Moro	OR	97039	
Latitude		Longitude	
45.47396		120.74158	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherman Junior/Senior High School

Final RVS Score

Final Type

Final Score

C2

1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherman Junior/Senior High School

Sher_sch02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
145	1956	1956	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53082	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Lateral-Force-Resistance in One Direction Only	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
Unreinforced Chimneys	None
None	None



S Vertical Irregularity Primary



S Falling Hazard



S Building Name



S Falling Hazard



S Field Verified Year Built
1956



S Primary Structural Type
B LEFT A RIGHT



NW Plan Irregularity Primary



NW Vertical Irregularity Primary



NE Plan Irregularity Primary
WING E HAS FEW N-S SHEAR WALLS



E Elevation View



Sherman Junior/Senior High School

Sherman County SD

Sher_sch02B

Building Type		County	
School		Sherman	
Street			
65912 High School Lp			
City	State	Zip	
Moro	OR	97039	
Latitude		Longitude	
45.47355		120.74197	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherman Junior/Senior High School

Final RVS Score

Final Type

Final Score

RM1

1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherman Junior/Senior High School

Sher_sch02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
145	1992	1956	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53082	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



S General Site
B TO A



SW Elevation View



S Falling Hazard



NW Elevation View



NE Plan Irregularity Primary

Sherman Junior/Senior High School

Sherman County SD

Sher_sch02C

Building Type		County	
School		Sherman	
Street			
65912 High School Lp			
City	State	Zip	
Moro	OR	97039	
Latitude		Longitude	
45.47442		120.74098	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	0	0	0	1.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherman Junior/Senior High School

Final RVS Score

Final Type

Final Score

C2

1.6

FEMA-154 Collapse Potential

Moderate (>1%)



Sher_sch02



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
145		1956	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53082	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



NE Falling Hazard



SW Elevation View

