

Netarts-Oceanside RFPD Station #61 Hall

Till_fir03A

Netarts - Oceanside RFPD

Building Type		County	
Fire - RFPD		Tillamook	
Street			
1235 5th St Loop			
City	State	Zip	
Netarts	OR	97143	
Latitude		Longitude	
45.43671		123.94796	
Tracking Code		Inspection Date	
RVS in 2006		9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Netarts-Oceanside RFPD Station #61 Hall

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Netarts-Oceanside RFPD Station #61 Hall

Till_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



SW Elevation View



SE Elevation View

Netarts-Oceanside RFPD Station #61 Garage

Till_fir03B

Netarts - Oceanside RFPD

Building Type		County	
Fire - RFPD		Tillamook	
Street			
1235 5th St Loop			
City	State	Zip	
Netarts	OR	97143	
Latitude		Longitude	
45.43685		123.948	
Tracking Code		Inspection Date	
RVS in 2006		9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Netarts-Oceanside RFPD Station #61 Garage

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Netarts-Oceanside RFPD Station #61 Garage

Till_fir03B


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
Torsion: Eccentric Stiffness	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



W Primary Structural Type



N Primary Structural Type
PILASTERS



W Building Name

Netarts-Oceanside RFPD Station #61 Office

Till_fir03C

Netarts - Oceanside RFPD

Building Type		County	
Fire - RFPD		Tillamook	
Street			
1235 5th St Loop			
City	State	Zip	
Netarts	OR	97143	
Latitude		Longitude	
45.43674		123.94808	
Tracking Code		Inspection Date	
RVS in 2006		9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Netarts-Oceanside RFPD Station #61 Office

Final RVS Score

Final Type

Final Score

W1

3.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Vertical Irregularity Primary