

City Of Garibaldi Fire Department / City Hall / Police

City of Garibaldi

Till_fir05A

Building Type Fire - City	County Tillamook	
Street 107 6th St		
City Garibaldi	State OR	Zip 97118
Latitude 45.55983	Longitude 123.91425	
Tracking Code RVS in 2006	Inspection Date 9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

City Of Garibaldi Fire Department /
City Hall / Police

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

City Of Garibaldi Fire Department / City Hall / Police

Till_fir05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1950	1950	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Building On Hill or Sloped Site	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
E	Elevation View	E	Field Verified Year Built DEDICATED 1955
			
NE	Vertical Irregularity Secondary	N	Elevation View
S	Building Name	E	Elevation View
			
S	Building Name		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

City Of Garibaldi Fire Department / City Hall / Police

City of Garibaldi

Till_fir05B

Building Type Fire - City	County Tillamook	
Street 107 6th St		
City Garibaldi	State OR	Zip 97118
Latitude 45.55962	Longitude 123.91418	
Tracking Code RVS in 2006	Inspection Date 9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

City Of Garibaldi Fire Department /
City Hall / Police

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

City Of Garibaldi Fire Department / City Hall / Police

Till_fir05B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1950	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Primary Structural Type	NE	Plan Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries