

Nestucca RFPD

|                              |                             |              |
|------------------------------|-----------------------------|--------------|
| Building Type<br>Fire - RFPD | County<br>Tillamook         |              |
| Street<br>35105 Brooten Road |                             |              |
| City<br>Pacific City         | State<br>OR                 | Zip<br>97135 |
| Latitude<br>45.20123         | Longitude<br>123.96119      |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>9/7/2006 |              |



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | 0          | -0.5       | 0        | 0          | 0      | 0      | -0.4   | 1.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Nestucca RFPD Pacific City #82

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 1.9         |

## FEMA-154 Collapse Potential

Moderate (&gt;1%)

No  
Planview  
Available



OregonGeology

# Nestucca RFPD Pacific City #82

Till\_fir11A

|  |                             |   |                    |
|--|-----------------------------|---|--------------------|
| Enrollment   | Year Built (Field Verified) | Year Built (Alt. Source)  | Est. Decade Built  |
|  |                             |   | 1960               |
| Total Area (square ft)   | Number of Stories           | Basement  | Pounding Potential |
|  | 2                           | No  | No                 |
| Plan Irregularities  |                             | Vertical Irregularities   |                    |
| Torsion: Eccentric Stiffness   |                             | None  |                    |
| None   |                             | None  |                    |
| None   |                             | None  |                    |
| Falling Hazards  |                             | Poor Conditions   |                    |
| None   |                             | None  |                    |
| None   |                             | None  |                    |
| None   |                             | None  |                    |
|    |                             |  |                    |
| E Primary Structural Type  |                             | SE Elevation View   |                    |
|  |                             | W Building Name   |                    |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Nestucca RFPD

|                              |                             |              |
|------------------------------|-----------------------------|--------------|
| Building Type<br>Fire - RFPD | County<br>Tillamook         |              |
| Street<br>35105 Brooten Road |                             |              |
| City<br>Pacific City         | State<br>OR                 | Zip<br>97135 |
| Latitude<br>45.20107         | Longitude<br>123.96116      |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>9/7/2006 |              |



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W1   | 4.4         | 0          | -0.5       | 0        | 0          | 0      | 0      | 0      | 3.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Nestucca RFPD Pacific City #82

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1         | 3.9         |

## FEMA-154 Collapse Potential

Low (&lt;1%)

No  
Planview  
Available



Oregon Geology

# Nestucca RFPD Pacific City #82

Till\_fir11B

|  |                             |   |                           |
|--|-----------------------------|---|---------------------------|
| Enrollment   | Year Built (Field Verified) | Year Built (Alt. Source)  | Est. Decade Built         |
|  |                             |   | 1940                      |
| Total Area (square ft)   | Number of Stories           | Basement  | Pounding Potential        |
|  | 1                           | No  | No                        |
| Plan Irregularities  |                             | Vertical Irregularities   |                           |
| Torsion: Eccentric Stiffness   |                             | None  |                           |
| None   |                             | None  |                           |
| None   |                             | None  |                           |
| Falling Hazards  |                             | Poor Conditions   |                           |
| None   |                             | Visible Dry Rot   |                           |
| None   |                             | None  |                           |
| None   |                             | None  |                           |
|  |                             |  |                           |
| NE   | Primary Structural Type     | SW  | Plan Irregularity Primary |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries