

# Nestucca RFPD Sandlake #85

Till\_fir12A

Nestucca RFPD

Building Type	County		
Fire - RFPD	Tillamook		
Street			
20965 Sandlake Road			
City	State	Zip	
Sandlake	OR	97108	
Latitude	Longitude		
45.30347	123.9223		
Tracking Code	Inspection Date		
RVS in 2006	9/7/2006		



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	0	0	0	0	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nestucca RFPD Sandlake #85

## Final RVS Score

Final Type	Final Score
W1	1.9

## FEMA-154 Collapse Potential

Moderate (>1%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Nestucca RFPD Sandlake #85

Till\_fir12A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Internal Discontinuous Diaphram (large internal opening)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Elevation View		W Building Name	
			
SW Elevation View		W Vertical Irregularity Primary	
			
S Primary Structural Type PLYWOOD PANELS ON INSIDE OF WALLS IN GARAGE			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries