

Nestucca RFPD

Building Type Fire - RFPD	County Tillamook	
Street 20055 Blaine Road		
City Beaver	State OR	Zip 97108
Latitude 45.27669	Longitude 123.824	
Tracking Code RVS in 2006	Inspection Date 9/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nestucca RFPD Beaver #83

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



No
Planview
Available



OregonGeology

Nestucca RFPD Beaver #83

Till_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Torsion: Eccentric Stiffness		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
	SW Plan Irregularity Primary		SW Vertical Irregularity Primary
	W Primary Structural Type OSB SHEATHING		
	N Plan Irregularity Secondary		N Building Name
	N Primary Structural Type OSB SHEATHING		
	E Elevation View		E Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nestucca RFPD

Building Type Fire - RFPD	County Tillamook	
Street 20055 Blaine Road		
City Beaver	State OR	Zip 97108
Latitude 45.27654	Longitude 123.82382	
Tracking Code RVS in 2006	Inspection Date 9/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nestucca RFPD Beaver #83

Final RVS Score

Final Type	Final Score
W1	6.3

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



Oregon Geology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Primary Structural Type	SE	Elevation View

