

Liberty Elementary School

Tillamook SD 9

Till_sch11A

Building Type School	County Tillamook	
Street 1700 9th St		
City Tillamook	State OR	Zip 97141
Latitude 45.45199	Longitude 123.84673	
Tracking Code SER & RVS2006	Inspection Date 9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Liberty Elementary School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Liberty Elementary School

Till_sch11A

Enrollment 201	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1960
Total Area (square ft) 26500	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Plan Irregularity Primary		SW Elevation View	
		SE Primary Structural Type STUCCO END WALL	
			
N Vertical Irregularity Primary		NW Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Liberty Elementary School

Tillamook SD 9

Till_sch1B

Building Type School	County Tillamook	
Street 1700 9th St		
City Tillamook	State OR	Zip 97141
Latitude 45.45226	Longitude 123.84641	
Tracking Code SER & RVS2006	Inspection Date 9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Liberty Elementary School

Final RVS Score

Final Type	Final Score
W2	4.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Liberty Elementary School

Till_sch11B

Enrollment 201	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1980
Total Area (square ft) 26500	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other (Adjacent Build/Entity) None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Plan Irregularity Primary		NW Vertical Irregularity Secondary	

Liberty Elementary School

Tillamook SD 9

Till_sch11C

Building Type School	County Tillamook	
Street 1700 9th St		
City Tillamook	State OR	Zip 97141
Latitude 45.45256	Longitude 123.84687	
Tracking Code SER & RVS2006	Inspection Date 9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	-1	0	0	-0.8	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Liberty Elementary School

Final RVS Score

Final Type	Final Score
W2	0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Liberty Elementary School

Till_sch11C

Enrollment 201	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1920
Total Area (square ft) 26500	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
SE Vertical Irregularity Primary	NW Plan Irregularity Primary	SW Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries