

Good Shepherd Community Hospital - Hermiston

NFP - Lutheran Affiliation

Umat_hos01A

Building Type	County	
Hospital	Umatilla	
Street		
610 Nw 11Th St		
City	State	Zip
Hermiston	OR	97838
Latitude	Longitude	
45.84706	119.30833	
Tracking Code	Inspection Date	
RVS in 2006	8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	C1	3	-2	-0.5	0	0	-0.6	0	0	-0.1

Good Shepherd Community Hospital - Hermiston

Final RVS Score

Final Type	Final Score
C1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Good Shepherd Community Hospital - Hermiston

Umat_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
158577	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Good Shepherd Community Hospital - Hermiston

NFP - Lutheran Affiliation

Umat_hos01B

Building Type	County	
Hospital	Umatilla	
Street		
610 Nw 11Th St		
City	State	Zip
Hermiston	OR	97838
Latitude	Longitude	
45.84638	119.30919	
Tracking Code	Inspection Date	
RVS in 2006	8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	W2	4.8	-3	-0.5	0	1.6	-0.8	0	0	2.1
Tertiary		0	0	0	0	0	0	0	0	0

Good Shepherd Community Hospital - Hermiston

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Good Shepherd Community Hospital - Hermiston

Umat_hos01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
158577	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Elevation View	W	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Good Shepherd Community Hospital - Hermiston

NFP - Lutheran Affiliation

Umat_hos01C

Building Type	County	
Hospital	Umatilla	
Street		
610 Nw 11Th St		
City	State	Zip
Hermiston	OR	97838
Latitude	Longitude	
45.84732	119.30795	
Tracking Code	Inspection Date	
RVS in 2006	8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	S2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3

Good Shepherd Community Hospital - Hermiston

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Good Shepherd Community Hospital - Hermiston

Umat_hos01C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
158577	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries