

Sherwood Heights Elementary School

Pendleton SD 16

Umat_sch10A

Building Type	County
School	Umatilla
Street	
3111 Sw Marshall Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.6536	118.81559
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	0	0	1.3
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood Heights Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Heights Elementary School

Umat_sch10A

Enrollment 373	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft) 37581	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: U shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Plan Irregularity Primary			

Sherwood Heights Elementary School

Pendleton SD 16

Umat_sch10B

Building Type	County
School	Umatilla
Street	
3111 Sw Marshall Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.65381	118.81607
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	0	0	1.3
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood Heights Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Sherwood Heights Elementary School

Umat_sch10B

Enrollment 373	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:U shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Vertical Irregularity Primary		 W Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Heights Elementary School

Pendleton SD 16

Umat_sch10C

Building Type	County
School	Umatilla
Street	
3111 Sw Marshall Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.65334	118.81608
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	S2	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood Heights Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential


Moderate (>1%)



OregonGeology

Sherwood Heights Elementary School

Umat_sch10C

Enrollment 373	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Heights Elementary School

Pendleton SD 16

Umat_sch10D

Building Type	County
School	Umatilla
Street	
3111 Sw Marshall Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.65352	118.81541
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	0	0	0	0	1.2
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood Heights Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Sherwood Heights Elementary School

Umat_sch10D

Enrollment 373	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Heights Elementary School

Pendleton SD 16

Umat_sch10E

Building Type	County
School	Umatilla
Street	
3111 Sw Marshall Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.65364	118.81619
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	1.6	0	0	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood Heights Elementary School

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Sherwood Heights Elementary School

Umat_sch10E

Enrollment 373	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built 1980
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 NW General Site			