

# Freewater Elementary School

Milton-Freewater Unified SD 7

Umat\_sch15A

Building Type		County	
School		Umatilla	
Street			
17 Nw 8th Ave			
City	State	Zip	
Milton-Freewater	OR	97862	
Latitude		Longitude	
45.94337		118.39825	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Freewater Elementary School

## Final RVS Score

Final Type

Final Score

URM

0.2

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
332		1909	1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31555	2	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None




NE Elevation View

# Freewater Elementary School

Milton-Freewater Unified SD 7

Umat\_sch15B

Building Type		County	
School		Umatilla	
Street			
17 Nw 8th Ave			
City		State	Zip
Milton-Freewater		OR	97862
Latitude		Longitude	
45.94362		118.39818	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary	C1	3	-2	-0.5	0	0	0	-1	0	-0.5

Freewater Elementary School

## Final RVS Score

Final Type

Final Score

C1

-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
332		1909	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Other: Smokestack	None
None	None
None	None



NE Falling Hazard



N Primary Structural Type



# Freewater Elementary School

Umat\_sch15C

Milton-Freewater Unified SD 7

Building Type		County	
School		Umatilla	
Street			
17 Nw 8th Ave			
City		State	Zip
Milton-Freewater		OR	97862
Latitude		Longitude	
45.9436		118.39871	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	-1.2	0	0.6
Secondary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Tertiary		0	0	0	0	0	0	0	0	0

Freewater Elementary School

## Final RVS Score

Final Type

Final Score

RM1

0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
332		1909	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View



S Elevation View

