

Lincoln Primary School

Pendleton SD 16

Umat_sch30A

Building Type School	County Umatilla	
Street 107 NW 10th St		
City Pendleton	State OR	Zip 97801
Latitude 45.67269	Longitude 118.79774	
Tracking Code RVS in 2006	Inspection Date 8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	0	0	0.7
Secondary	W2	4.8	-3	-0.5	-0.2	0	0	0	0	1.1
Tertiary	RM1	3.6	-2	-0.5	-0.4	0	0	0	0	0.7

Lincoln Primary School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lincoln Primary School

Umat_sch30A

Enrollment 174	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1930
Total Area (square ft) 29806	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: E Shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Elevation View		E Elevation View	
		E Elevation View	

Lincoln Primary School

Pendleton SD 16

Umat_sch30B

Building Type School	County Umatilla	
Street 107 NW 10th St		
City Pendleton	State OR	Zip 97801
Latitude 45.67226	Longitude 118.79765	
Tracking Code RVS in 2006	Inspection Date 8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Primary School

Final RVS Score

Final Type	Final Score
W2	1.8

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Lincoln Primary School

Umat_sch30B

Enrollment 174	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1940
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Other		W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lincoln Primary School

Pendleton SD 16

Umat_sch30C

Building Type School	County Umatilla	
Street 107 NW 10th St		
City Pendleton	State OR	Zip 97801
Latitude 45.673	Longitude 118.79777	
Tracking Code RVS in 2006	Inspection Date 8/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	1.6	0	0	0	5.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Primary School

Final RVS Score

Final Type	Final Score
W2	5.9

FEMA-154 Collapse Potential

Low (<1%)



Umat_sch30

0 200 400
feet



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lincoln Primary School

Umat_sch30C

Enrollment 174	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1980
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards Other: Smokestack None None		Poor Conditions None None None	
			
W Falling Hazard adj. power building	E Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries