

Imbler High School

Imbler SD 11

Unio_sch06A

Building Type School	County Union	
Street 6th St and Esther Ave		
City Imbler	State OR	Zip 97841
Latitude 45.46182	Longitude 117.96582	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Imbler High School

Final RVS Score

Final Type	Final Score
URM	0.2

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Imbler High School

Unio_sch06A

Enrollment 147	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1910
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		Cracks	
None		None	
None		None	
			
SE	Falling Hazard	S	Poor Condition
			
		SW	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Imbler High School

Imbler SD 11

Unio_sch06B

Building Type School	County Union	
Street 6th St and Esther Ave		
City Imbler	State OR	Zip 97841
Latitude 45.46206	Longitude 117.9659	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Imbler High School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Imbler High School

Unio_sch06B

Enrollment 147	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1930
Total Area (square ft)	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions Other None None	
 SW Elevation View		 NW Elevation View	
		 N Poor Condition stucco bubbling off	
 NE Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Imbler High School

Imbler SD 11

Unio_sch06C

Building Type	County	
School	Union	
Street		
6th St and Esther Ave		
City	State	Zip
Imbler	OR	97841
Latitude	Longitude	
45.46203	117.96549	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Imbler High School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Imbler High School

Unio_sch06C

Enrollment 147	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: T shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 S Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Imbler High School

Imbler SD 11

Unio_sch06D

Building Type School	County Union	
Street 6th St and Esther Ave		
City Imbler	State OR	Zip 97841
Latitude 45.46248	Longitude 117.96557	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Imbler High School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Imbler High School

Unio_sch06D

Enrollment 160	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries