

# Stella Mayfield Elementary School

Elgin SD 23

Unio\_sch08A

Building Type School	County Union	
Street 1111 Division St		
City Elgin	State OR	Zip 97827
Latitude 45.56532	Longitude 117.921	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

**Stella Mayfield Elementary School**

**Final RVS Score**

Final Type	Final Score
C2	-0.1

**FEMA-154 Collapse Potential**

Very High (100%)
------------------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Stella Mayfield Elementary School

Unio\_sch08A

Enrollment 285	Year Built (Field Verified) 1947	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 45300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View		 NE Elevation View	

# Stella Mayfield Elementary School

Unio\_sch08B

Elgin SD 23

Building Type School	County Union	
Street 1111 Division St		
City Elgin	State OR	Zip 97827
Latitude 45.56504	Longitude 117.92114	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate											Stella Mayfield Elementary School	
FEMA 154 Rapid Visual Screening Score Card											Final RVS Score	
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1	C2	-0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1		
Tertiary		0	0	0	0	0	0	0	0	0		Very High (100%)



# Stella Mayfield Elementary School

Unio\_sch08B

Enrollment 285	Year Built (Field Verified) 1947	Year Built (Alt. Source) 1947	Est. Decade Built 1950
Total Area (square ft) 45300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Building Name		 SW Elevation View	

# Stella Mayfield Elementary School

Unio\_sch08C

Elgin SD 23

Building Type School	County Union	
Street 1111 Division St		
City Elgin	State OR	Zip 97827
Latitude 45.56556	Longitude 117.92139	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stella Mayfield Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.1

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Stella Mayfield Elementary School

Unio\_sch08C

Enrollment 285	Year Built (Field Verified) 1947	Year Built (Alt. Source) 1947	Est. Decade Built 1960
Total Area (square ft) 45300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 NW Elevation View		 NE Elevation View	