

# Wallowa Elementary School

Wallowa SD 12

Wall\_sch02A

Building Type School	County Wallowa	
Street 315 1st St		
City Wallowa	State OR	Zip 97885
Latitude 45.57061	Longitude 117.53285	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wallowa Elementary School

### Final RVS Score

Final Type	Final Score
URM	0.2

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Wallowa Elementary School

Wall\_sch02A

Enrollment 143	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1922	Est. Decade Built 1920
Total Area (square ft) 43098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Across Front of Building		None	
None		None	
None		None	
 E Elevation View		 NE Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Wallowa Elementary School

Wallowa SD 12

Wall\_sch02B

Building Type School	County Wallowa	
Street 315 1st St		
City Wallowa	State OR	Zip 97885
Latitude 45.57072	Longitude 117.53332	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wallowa Elementary School

## Final RVS Score

Final Type	Final Score
C2	-0.5

## FEMA-154 Collapse Potential

Very High (100%)



Oregon Geology

# Wallowa Elementary School

Wall\_sch02B

Enrollment 143	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 43098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>N Elevation View</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Wallowa Elementary School

Wallowa SD 12

Wall\_sch02C

Building Type School	County Wallowa	
Street 315 1st St		
City Wallowa	State OR	Zip 97885
Latitude 45.57087	Longitude 117.53273	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wallowa Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Wallowa Elementary School

Wall\_sch02C

Enrollment 143	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1922	Est. Decade Built 1950
Total Area (square ft) 43098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Elevation View			

# Wallowa Elementary School

Wallowa SD 12

Wall\_sch02D

Building Type School	County Wallowa	
Street 315 1st St		
City Wallowa	State OR	Zip 97885
Latitude 45.57085	Longitude 117.53201	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wallowa Elementary School

## Final RVS Score

Final Type	Final Score
W2	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Wallowa Elementary School

Wall\_sch02D

Enrollment 143	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1922	Est. Decade Built 1940
Total Area (square ft) 43098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Elevation View		 W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Wallowa Elementary School

Wallowa SD 12

Wall\_sch02E

Building Type School	County Wallowa	
Street 315 1st St		
City Wallowa	State OR	Zip 97885
Latitude 45.57085	Longitude 117.53132	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wallowa Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.1

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Wallowa Elementary School

Wall\_sch02E

Enrollment 143	Year Built (Field Verified) 1922	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft) 43098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped Reentrant Corners: L Shaped None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>E Elevation View</p>			