

TVF & R - Station 62 Command Center

Tualatin Valley F&R

Wash_fir18A

Building Type Fire - RFPD	County Washington	
Street 20665 SW Blanton St		
City Aloha	State OR	Zip 97007
Latitude 45.49259	Longitude 122.88941	
Tracking Code To be Re-built	Inspection Date 6/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 62 Command Center

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 62 Command Center

Wash_fir18A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1980	1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
36000	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



SW General Site



NW Vertical Irregularity Primary



SW Falling Hazard



S Vertical Irregularity Primary



NE Falling Hazard



N Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 62 Command Center

Tualatin Valley F&R

Wash_fir18B

Building Type Fire - RFPD	County Washington	
Street 20665 SW Blanton St		
City Aloha	State OR	Zip 97007
Latitude 45.49267	Longitude 122.88916	
Tracking Code To be Re-built	Inspection Date 6/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 62 Command Center

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 62 Command Center

Wash_fir18B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
36000	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Elevation View S3 connects to RM1			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 62 Command Center

Tualatin Valley F&R

Wash_fir18C

Building Type Fire - RFPD	County Washington	
Street 20665 SW Blanton St		
City Aloha	State OR	Zip 97007
Latitude 45.49251	Longitude 122.88894	
Tracking Code To be Re-built	Inspection Date 6/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 62 Command Center

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 62 Command Center

Wash_fir18C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
36000	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		Other	
None		None	
None		None	
 S Primary Structural Type		 SW Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries