

Gaston RFPD

Wash_fir20A

Gaston RFPD

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type Fire - RFPD | County Washington | |
| Street 102 E Main | | |
| City Gaston | State OR | Zip 97119 |
| Latitude 45.43695 | Longitude 123.13862 | |
| Tracking Code RVS in 2006 | Inspection Date 7/6/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 2.8 | -1 | 0 | 0 | 0 | -0.4 | 0 | 0 | 1.4 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Gaston RFPD

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 1.4 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

| | | | |
|--|-----------------------------|--|-------------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | Yes |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners:L shaped (Adjacent Build/Entity) | | Steps in Elevation View: Single Change | |
| Lateral-Force-Resistance in One Direction Only | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| S | General Site | SE | Primary Structural Type |
| | |  | |
| | | SE | General Site |



Gaston RFPD

Wash_fir20B

Gaston RFPD

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type Fire - RFPD | County Washington | |
| Street 102 E Main | | |
| City Gaston | State OR | Zip 97119 |
| Latitude 45.43697 | Longitude 123.13842 | |
| Tracking Code RVS in 2006 | Inspection Date 7/6/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 4.4 | 0 | 0 | 0 | 2.4 | 0 | 0 | 0 | 6.8 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Gaston RFPD

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 6.8 |

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

| | | | |
|--|-----------------------------|---|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | Yes |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners:L shaped (Adjacent Build/Entity) | | None | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| NW Plan Irregularity Primary | | NE Elevation View | |

