

Washington County RFPD 2

Washington County RFPD

Wash_fir24A

Building Type Fire - RFPD	County Washington	
Street 15200 Sw Midway Rd		
City Hillsboro	State OR	Zip 97123
Latitude 45.41042	Longitude 122.95984	
Tracking Code RVS in 2006	Inspection Date 7/4/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Washington County RFPD 2

Final RVS Score

Final Type	Final Score
S3	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Washington County RFPD 2

Wash_fir24A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Vertical Irregularity Primary		SE Elevation View	
		SE Pounding Potential	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries