

Providence St. Vincent Hospital

Providence Health System - Oregon NFP

Wash_hos02A

Building Type Hospital	County Washington	
Street 9205 SW Barnes Rd		
City Portland	State OR	Zip 97225
Latitude 45.51049	Longitude 122.77174	
Tracking Code New Building	Inspection Date 6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.1	-1.5	-0.5	0	0	-0.4	0	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Providence St. Vincent Hospital

Final RVS Score

Final Type	Final Score
C1	0.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence St. Vincent Hospital

Wash_hos02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1971	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	9	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Short Columns	
None		Sloped or Inclined Walls	
None		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Falling Hazards		Poor Conditions	
Other: Heavy cornice or other overhead decoration		None	
None		None	
None		None	
			
E Field Verified Year Built 1971		E Pounding Potential	
			
SE Pounding Potential over main ent			
			
S Pounding Potential		S Pounding Potential out of plain elements are separated by ~1".	
			
NW Pounding Potential			
			
NE Elevation View new const on the right edge of pic.		E Elevation View Mech building and loading dock, not RVsed	
			
NE Elevation View Bldg A is in upper left of photo			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence St. Vincent Hospital

Wash_hos02A



N General Site

New construction 2004 on left side of photo.

Mech bldg in foreground



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence St. Vincent Hospital

Providence Health System - Oregon NFP

Wash_hos02B

Building Type Hospital	County Washington	
Street 9205 SW Barnes Rd		
City Portland	State OR	Zip 97225
Latitude 45.51024	Longitude 122.77198	
Tracking Code New Building	Inspection Date 6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Providence St. Vincent Hospital

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence St. Vincent Hospital

Wash_hos02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1971	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:U shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Non-Parallel System		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Primary Structural Type	S	Plan Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Providence St. Vincent Hospital

Providence Health System - Oregon NFP

Wash_hos02D

Building Type	County	
Hospital	Washington	
Street		
9205 SW Barnes Rd		
City	State	Zip
Portland	OR	97225
Latitude	Longitude	
45.51056	122.7731	
Tracking Code	Inspection Date	
New Building	6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.2	-1	-0.5	0	2.4	-0.4	0	0	3.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Providence St. Vincent Hospital

Final RVS Score

Final Type	Final Score
C2	3.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Providence St. Vincent Hospital

Wash_hos02D

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1971	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
N	Primary Structural Type	SE	Falling Hazard



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries