

Gaston Police Dept

City of Gaston

Wash_pol11A

Building Type Police - City	County Washington	
Street 116 Front St		
City Gaston	State OR	Zip 97119
Latitude 45.43777	Longitude 123.14028	
Tracking Code RVS in 2006	Inspection Date 7/6/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary	C2	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Gaston Police Dept

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Gaston Police Dept

Wash_pol11A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		Poor Concrete	
None		None	
None		None	



NE Elevation View



NW Elevation View



NW Primary Structural Type



NE Poor Condition
very worn C2 wall against RM1.

Bad photo, there is a C2 wall on the right side of the photo with



NE Building Name



N Falling Hazard



NW Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries