

# Mooberry Elementary School

Hillsboro SD 1J

Wash\_sch05A

Building Type School	County Washington	
Street 1230 Ne 10th Ave		
City Hillsboro	State OR	Zip 97124
Latitude 45.53383	Longitude 122.97179	
Tracking Code Already Retrofitted	Inspection Date 7/10/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Secondary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Tertiary	URM	1.8	0	-0.5	0	0	0	-0.6	0	0.7


Mooberry Elementary School

## Final RVS Score

Final Type	Final Score
URM	0.7

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Mooberry Elementary School

Wash\_sch05A

Enrollment 543	Year Built (Field Verified) 1963	Year Built (Alt. Source) 1963	Est. Decade Built 1960
Total Area (square ft) 215000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities None None None	
Falling Hazards Unreinforced Chimneys Other: Brick Veneer Other: General		Poor Conditions Differential Settlement with Damage Poor Masonry None	
			
S Building Name	W General Site	SW Falling Hazard	
			
W Field Verified Year Built 1963	N Primary Structural Type Wood	W General Site	
			
NW General Site	NW Poor Condition Wall sliding off foundation	N Poor Condition full view of last photo	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Mooberry Elementary School

Wash\_sch05A



NW General Site



NE Pounding Potential



N Poor Condition



NW Poor Condition  
Other wall sliding off foundation



SW General Site



E Falling Hazard

# Mooberry Elementary School

Hillsboro SD 1J

Wash\_sch05B

Building Type School	County Washington	
Street 1230 Ne 10th Ave		
City Hillsboro	State OR	Zip 97124
Latitude 45.53426	Longitude 122.97196	
Tracking Code Already Retrofitted	Inspection Date 7/10/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Tertiary		0	0	0	0	0	0	0	0	0

Mooberry Elementary School

## Final RVS Score

Final Type	Final Score
S3	2.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Mooberry Elementary School

Wash\_sch05B

Enrollment 543	Year Built (Field Verified) 1963	Year Built (Alt. Source) 1963	Est. Decade Built 1970
Total Area (square ft) 215000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 SE Primary Structural Type		 W General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries