

Brookwood Elementary School

Hillsboro SD 1J

Wash_sch22A

Building Type		County	
School		Washington	
Street			
3960 Se Cedar St			
City	State	Zip	
Hillsboro	OR	97123	
Latitude		Longitude	
45.51537		122.94218	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Brookwood Elementary School

Final RVS Score

Final Type

Final Score

C2

0.7

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
558		1953	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40641	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions