

Harvey Clarke Elementary School

Forest Grove SD 15

Wash_sch25A

Building Type School	County Washington	
Street 2516 N B St		
City Forest Grove	State OR	Zip 97116
Latitude 45.52669	Longitude 123.11666	
Tracking Code RVS in 2006	Inspection Date 7/12/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Harvey Clarke Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harvey Clarke Elementary School

Wash_sch25A

Enrollment 415	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1950
Total Area (square ft) 54110	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
Unreinforced Chimneys		None	
None		None	
			
N General Site	NE Falling Hazard	W General Site	
			
NW General Site	W Primary Structural Type Wood	W General Site	
			
SW General Site	W General Site	SW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harvey Clarke Elementary School

Wash_sch25A



NW General Site



E Building Name

Harvey Clarke Elementary School

Forest Grove SD 15

Wash_sch25B

Building Type School	County Washington	
Street 2516 N B St		
City Forest Grove	State OR	Zip 97116
Latitude 45.52685	Longitude 123.11617	
Tracking Code RVS in 2006	Inspection Date 7/12/2006	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0



Harvey Clarke Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harvey Clarke Elementary School

Wash_sch25B

Enrollment 415	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1950
Total Area (square ft) 54110	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 N Primary Structural Type		 N Vertical Irregularity Primary	
		 NW General Site	

Harvey Clarke Elementary School

Forest Grove SD 15

Wash_sch25C

Building Type School	County Washington	
Street 2516 N B St		
City Forest Grove	State OR	Zip 97116
Latitude 45.52631	Longitude 123.11656	
Tracking Code RVS in 2006	Inspection Date 7/12/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Harvey Clarke Elementary School

Final RVS Score

Final Type	Final Score
S3	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harvey Clarke Elementary School

Wash_sch25C

Enrollment 415	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1980
Total Area (square ft) 54110	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 <p>SW Pounding Potential</p>			