


Bridgeport Elementary School

Wash_sch28A

Tigard-Tualatin SD 23J

| | | | |
|--------------------|-------|-----------------|--|
| Building Type | | County | |
| School | | Washington | |
| Street | | | |
| 5505 Sw Borland Rd | | | |
| City | State | Zip | |
| Tualatin | OR | 97062 | |
| Latitude | | Longitude | |
| 45.37844 | | 122.7326 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 7/11/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 2.4 | 0 | -0.8 | 0 | 2.9 |
| Secondary | C2 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | -0.6 | 0 | 0.7 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Bridgeport Elementary School

Final RVS Score

Final Type

Final Score

C2

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 500 | 1982 | 1982 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 64513 | 1 | No | Yes |

| | |
|--|--|
| Plan Irregularities | Vertical Irregularities |
| Reentrant Corners: Other | Steps in Elevation View: 2 to 3 Changes |
| Reentrant Corners: Other (Adjacent Build/Entity) | Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) |
| None | None |

| | |
|---------------------|-----------------|
| Falling Hazards | Poor Conditions |
| Other: Brick Veneer | None |
| Other: General | None |
| None | None |



NW Primary Structural Type
W2



SW Plan Irregularity Primary



SW General Site



NW General Site



N General Site



NE Pounding Potential



E Plan Irregularity Primary



N Pounding Potential



SE General Site



NE General Site



Bridgeport Elementary School

Tigard-Tualatin SD 23J

Wash_sch28B

| | | | |
|--------------------|-------|-----------------|--|
| Building Type | | County | |
| School | | Washington | |
| Street | | | |
| 5505 Sw Borland Rd | | | |
| City | State | Zip | |
| Tualatin | OR | 97062 | |
| Latitude | | Longitude | |
| 45.37789 | | 122.73264 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 7/11/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | PC1 | 2.6 | 0 | -0.5 | 0 | 0 | 0 | -0.6 | 0 | 1.5 |
| Secondary | W2 | 3.8 | -2 | -0.5 | 0 | 2.4 | 0 | -0.8 | 0 | 2.9 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Bridgeport Elementary School

Final RVS Score

Final Type

Final Score

PC1

1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 500 | 1986 | 1982 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 64513 | 1 | No | Yes |

| | |
|------------------------------|--|
| Plan Irregularities | Vertical Irregularities |
| Torsion: Eccentric Stiffness | Steps in Elevation View: Single Change |
| None | None |
| None | None |

| | |
|---------------------|-----------------|
| Falling Hazards | Poor Conditions |
| Other: Brick Veneer | None |
| Other: General | None |
| None | None |



NW Plan Irregularity Primary
confirmed W2 with brick veneer on right. Tilt upon left.



N Primary Structural Type



NE General Site
covered play area not RVSeD



E General Site



SE General Site

