

Hazeldale Elementary School

Beaverton SD 48J

Wash_sch55A

Building Type		County	
School		Washington	
Street			
20080 Sw Farmington Rd			
City	State	Zip	
Aloha	OR	97007	
Latitude		Longitude	
45.46907		122.88296	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hazeldale Elementary School

Final RVS Score

Final Type

Final Score

URM

-0.1

FEMA-154 Collapse Potential

Moderate (>1%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
599		1949	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
51250	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions