

Sherwood Middle School

Sherwood SD 88J

Wash_sch78A

Building Type School	County Washington	
Street 21970 SW Sherwood Blvd		
City Sherwood	State OR	Zip 97140
Latitude 45.35927	Longitude 122.84127	
Tracking Code RVS in 2006	Inspection Date 7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
PC1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Sherwood Middle School

Wash_sch78A

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1980
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW General Site		 SW Plan Irregularity Primary	
 N Elevation View		 NE Plan Irregularity Primary	
 SW Primary Structural Type		 S General Site	
 N Primary Structural Type		 NE Pounding Potential	



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Sherwood SD 88J

Wash_sch78B

Building Type	County	
School	Washington	
Street		
21970 SW Sherwood Blvd		
City	State	Zip
Sherwood	OR	97140
Latitude	Longitude	
45.35888	122.84093	
Tracking Code	Inspection Date	
RVS in 2006	7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	-0.4	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
RM1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Sherwood Middle School

Wash_sch78B

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1980
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE General Site			

Sherwood Middle School

Sherwood SD 88J

Wash_sch78C

Building Type	County	
School	Washington	
Street		
21970 SW Sherwood Blvd		
City	State	Zip
Sherwood	OR	97140
Latitude	Longitude	
45.35877	122.84166	
Tracking Code	Inspection Date	
RVS in 2006	7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Wash_sch78C

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1930
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity)		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes	
Non-Parallel System None		None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Building Name correct address		 NE Secondary Structural Type RM1 on E. wall	
		 W Vertical Irregularity Secondary short columns ??	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Sherwood SD 88J

Wash_sch78D

Building Type	County	
School	Washington	
Street		
21970 SW Sherwood Blvd		
City	State	Zip
Sherwood	OR	97140
Latitude	Longitude	
45.35849	122.84104	
Tracking Code	Inspection Date	
RVS in 2006	7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	-0.4	0	0	1.4
Secondary	C2	2.8	-1	0	0	0	-0.4	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
RM1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Wash_sch78D

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1980
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View		 SE Vertical Irregularity Primary	 SE Other



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Sherwood SD 88J

Wash_sch78E

Building Type School	County Washington	
Street 21970 SW Sherwood Blvd		
City Sherwood	State OR	Zip 97140
Latitude 45.35899	Longitude 122.84153	
Tracking Code RVS in 2006	Inspection Date 7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Wash_sch78E

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1980
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent)	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sherwood Middle School

Sherwood SD 88J

Wash_sch78F

Building Type	County	
School	Washington	
Street		
21970 SW Sherwood Blvd		
City	State	Zip
Sherwood	OR	97140
Latitude	Longitude	
45.35852	122.84178	
Tracking Code	Inspection Date	
RVS in 2006	7/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Sherwood Middle School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Sherwood Middle School

Wash_sch78F

Enrollment 887	Year Built (Field Verified) 1936	Year Built (Alt. Source) 1936	Est. Decade Built 1960
Total Area (square ft) 90249	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions Cracks None None	
 NW Pounding Potential		 SW General Site	
		 SE Poor Condition each column shows cracks at base of windo level	
 SE General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries