

Carlton Fire Department

City of Carlton

Yamh_fir04A

Building Type	County
Fire - City	Yamhill
Street	
209 N Kutch St	
City	State Zip
Carlton	OR 97111
Latitude	Longitude
45.29463	123.17879
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	-1	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Carlton Fire Department

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Carlton Fire Department

Yamh_fir04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: Brick Veneer		None	
Parapets: Unreinforced Around Entire Building		None	
			
NE Elevation View		SE Elevation View	
		SW Primary Structural Type	
			
SW Elevation View		SW Falling Hazard	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries