

Carlton Elementary School

Yamhill-Carlton SD 1

Yamh_sch02A

Building Type	County	
School	Yamhill	
Street		
420 S 3rd		
City	State	Zip
Carlton	OR	97111
Latitude		Longitude
45.29097		123.17292
Tracking Code		Inspection Date
RVS in 2006		8/16/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Carlton Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Carlton Elementary School

Yamh_sch02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
350		1952	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
39480	2	Yes	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other (Adjacent Build/Entity)	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
Other: General	None
None	None



NW Elevation View



W Elevation View




SW Primary Structural Type



W Building Name



NW Basement



NW Vertical Irregularity Secondary
Built on hill



NE Elevation View



E Elevation View



NE Elevation View



E Falling Hazard



NE Falling Hazard




SE Falling Hazard



N Falling Hazard



N Plan Irregularity Primary



SE Other



Yamhill-Carlton SD 1

Yamh_sch02B

A photograph of a school courtyard. On the right, a long, single-story building with a covered walkway runs along the edge. The walkway is supported by light-colored columns. The building has several windows with dark frames. In the center of the courtyard, there are two wooden picnic tables. To the left of the picnic tables, there are several large potted plants and a small tree. The ground is paved with dark asphalt and light-colored concrete. A tall evergreen tree is visible in the background behind the building.

Carlton Elementary School

Final RVS Score

Final Type	Final Score
------------	-------------

2.4

LOW (<1%)



Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
350		1952	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
39480	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Primary Structural Type



NW Elevation View



W Building Quality
12" gap no pounding p.



NE Elevation View



SE Elevation View



E Building Quality

Carlton Elementary School

Yamhill-Carlton SD 1

Yamh_sch02C

Building Type		County	
School		Yamhill	
Street			
420 S 3rd			
City	State	Zip	
Carlton	OR	97111	
Latitude		Longitude	
45.29063		123.17312	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Carlton Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
350		1952	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
39480	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change
None	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



NE Elevation View



NE Pounding Potential



E General Site
no RVS mech rm



SE Elevation View



SE Secondary Structural Type
RM1 side



SE Elevation View



W Elevation View



SW Secondary Structural Type



W Secondary Structural Type



NW Plan Irregularity Secondary



NW Plan Irregularity Secondary



NE Plan Irregularity Secondary



SW Elevation View



NW Elevation View